

DRAFT COPY

DRAFT



NATIONAL IRON ORE MINING COMPANY

THE MINE & INDUSTRIAL FACILITIES



FOR

STATUS PURSUANT TO
THE REHABILITATION/REPAIR

AND

RE-OPERATIONALIZATION OF NIOMCO

NOVEMBER 2019

EXECUTIVE SUMMARY

The National Iron Ore Mining Project Itakpe was designed to produce and supply 2.15 million tonnes of 63 – 64% Fe iron ore concentrate for the first phase production of 1.3 million tonnes of liquid steel per annum at the Ajaokuta Steel Plant (ASP) as well as 0.55 million tonnes of 67 – 68% Fe iron ore superconcentrate for the production of 1.0 million tonnes of liquid steel per annum at the Delta Steel Plant (DSP). NIOMCO is also to sell to the international market after satisfying the local demand including the expanded demands of the National Steel Plants at the second and third phases for the Delta Steel Plant and Ajaokuta Steel Plant, respectively.

THE MINE

The mine operation began in 1981 with a total of 3,865,078 Tons produced within the 1981 and 2008. The Mine has been fully developed with 20% of the Mining Fleet on ground. However, this 20% Mining fleet were last procured in 1992 and 2003 and are due for major refurbishment or outright replacement. Most of the Laboratory equipment and tools are also obsolete needing replacement.

THE BENEFICIATION PLANT

The three process lines for the production of concentrates have been completed, culminating in the production of over 620,000 tonnes of 63-65% Fe concentrates from 1993 to April 2008. The condition of the plant is such that it would require some repairs and maintenance work to be done. The items and activities required to get the plant to a condition for production of iron ore concentrate are spelt out in the full report. The plant was left in a deplorable state and all stocked spare parts exhausted by the previous concessionaire.

The Weathered Ore Treatment Plant for improved process yield and efficiency as well as the Superconcentrate Plant for the production of 67 –68% Superconcentrates are yet to be completed.

ELECTRICAL FACILITIES

NIOMCO has an 11kV overhead network covering a distance of about 50km. It is fed by stepping down from 132kV through 2 x 30MVA main transformers and channeled to 65 Nos distribution transformers. The electrical units mostly cables, circuit breakers, limit switches, instrumentation, communication network of the plant had depreciated due to exposure to harsh conditions and age. Upgrading of Instrumentation and Control Systems, replacement of burnt and missing power and control cables, motors, pumps, etc are required.

ORE RAIL LINE

Also completed is the 52km Itakpe – Ajaokuta standard gauge Rail Line. This rail line equipped with 2 locomotives and 71 wagons was used in transporting the concentrate to Ajaokuta and Delta Steel Plant. This however has been transferred to the Ministry of Transport for use in passengers transport to Warri. Most of the wooden sleepers have been changed to concrete sleepers leaving out only the marshaling yard at Itakpe and Ajaokuta, it is advised to replace these wooden sleepers with concrete sleepers for durability considering the weight of the iron ore concentrate the wagons would be carrying and the fact that they are getting rotten. It is also to be noted that there is need to agree on a term with the Ministry of Transport on the usage of the rail when production starts. There should

be a very good communication link at the Control Towers between NIOMCO, Ajaokuta and the Ministry of Transport (Nigerian Railway) as it was with NIOMCO/Ajaokuta/ Julius Berger and also to intimate the Ministry of Transport of the release of the 2 Nos locomotive back to NIOMCO when production begins or procure new ones.

CONCLUSION

In operating and maintenance of this plant, there is the need to procure tools and some testing equipment. It is expected that once the company is reoperationalised, it will pursue its primary responsibility of meeting the 100% iron ore concentrates requirements of the Ajaokuta Steel Company of which the Itakpe Iron Ore mine is a captive mine and also to generate the urgently needed non-oil revenue and employment opportunities from the Company and associated upstream and downstream industries.

In this respect, the FGN should maintain the National Iron Ore Mining Company and the Ajaokuta Steel Company as National organizations, since separate ownership of the two companies will create undesirable bottlenecks in meeting the country's vision 2020:20 policy of becoming a regional/global iron and steel producer/consumer.


**NATIONAL IRON ORE MINING COMPANY LIMITED
DIAGNOSTIC TECHNICAL REPORT**

1.0. INTRODUCTION

1.1 OBJECTIVES OF NIOMCO

- To produce and supply 100% of the iron ore concentrate requirements of Ajaokuta Steel Company Limited (ASCL), amounting to 2.15 million tonnes of 63-64% Fe concentrates per year, to enable it produce 1.3 million tonnes of liquid steel per annum during its first phase production stage.
- To produce and supply 40% of the iron ore requirement of Delta Steel Company, (DSC), Limited, Aladja, amounting to 550,000 tonnes per year of 67-68% Fe grade super concentrate.
- To export the concentrate to the International Markets after satisfying the local demands including the expanded demands of the primary steel plants.
- To arrange and co-ordinate the exploration, exploitation and supply of raw materials required by the Nation's major steel plants. These raw materials include coking coal, limestone/marble, dolomite, refractory clays, manganese, bauxite, ferro-alloy materials, etc.

**2.0 NATIONAL IRON ORE MINING COMPANY – PROCESS FLOW
BENEFICIATION PROCESS FLOW**



3.0 HISTORICAL BACKGROUND

As a follow up to the First National Development Plan (1962 – 1968) that provided for the establishment of a steel complex utilizing Nigerian raw materials, the Federal Government of Nigeria (FGN) established the Nigerian Steel Development Authority (NSDA) in 1971 by Decree No. 19 as a platform to develop a National Steel Industry. After initial studies and favourable exploratory works, the NSDA was dissolved through decree No. 60 on the 19th September 1979 which also created in its place; the Ajaokuta Steel Company Ltd, the Delta Steel Company Ltd, the Rolling Mills at Katsina, Oshogbo and Jos, as well as the Associated Ores Mining Company Ltd (AOMC), which was later renamed National Iron Ore Mining Company Ltd (NIOMCO) in 1987 to streamline its activities.

Iron Ore Mining commenced in 1980 while construction of the Itakpe/Ajaokuta Ore Rail Line, the Osara Earth Dam, the Power Supply system and the Beneficiation Plant (Lines 1 and 2) were completed in 1989, 1990 & 1992 respectively culminating in the commissioning of concentrate production by the then Mr. President, Gen. Ibrahim Babangida on December 19th 1992. Beneficiation Plant Line 3 was later commissioned in 1993 and over 290,000 tonnes of concentrates was produced from 1993 to 1997.

Between 1980 and 1997, NIOMCO produced

- 9.02m tonnes of associated waste,
- 2.99 million tonnes of raw iron ore (ROM)
- 1.02 million tonnes was crushed
- 291,415 tonnes of concentrates between 1993 and 1997.
- Supplied about 12,000 tonnes of concentrates to ASCL in 1993 to test the handling facilities there.
- Sold 58,861 tonnes on credit to DSC between 1994 and 1996 from which billets of international standard was produced and dispatched to the inland rolling mills.
- 31,000 tonnes of concentrates was also sold to non-steel companies especially cement manufacturers and the oil pipe line industries in 2004 and first quarter of 2005.


Between 2005 and 2008, during the concession to GINL, NIOMCO produced

- 874,389 tonnes of raw iron ore (ROM)
- Crushed 1,804, 842 ROM
- 332,137 tonnes of concentrate.

During the concessioning of the plant to Global Steel Infrastructure Limited, the plant had also ran and concentrates produced. However, by the time the concession agreement was cancelled in 2008, the plant had been used up and mismanaged thereby leaving most of the equipment in a very bad state without any stocked up spares left behind.

4.0 ORGANISATIONAL STRUCTURE

The Company has eight department headed by a sole administrator's Office to coordinate the activities of the departments all aimed at the successful production of the final product (iron ore concentrate), maintenance of facilities, management of human resources and its welfare services. All these eight departments report its activities to the Office of the Sole Administrator/Chief Executive.



4.1. CURRENT STAFF STRENGTH

The current staff is 801 while the projected requirement of manpower for the optimal production of iron ore concentrate is 2500 employees comprising both the technical and non-technical personnel to keep up to the constant and uninterrupted production of iron ore concentrate for the Steel Plant.

5.0 ITAKPE IRON ORE DEPOSIT EAST PIT & WEST PIT

ESTIMATED TONNAGE RESERVES

| | |
|---|---------------------------|
| GEOLOGICAL RESERVE: | 200MILLION METRIC TONNES |
| MINEABLE RESERVE: | 145MILLION METRIC TONNES |
| MINED TO DATE: | 3.9MILLION METRIC TONNES |
| RUN OF MINE ORE CURRENTLY AVAILABLE FOR MINING: | 141 MILLION METRIC TONNES |

WEST PIT WORKED FROM INITIAL HEIGHT OF 375 Metres above the sea level to the present level of 320 Metres above the sea level.

EAST PIT WORKED FROM THE INITIAL HEIGHT OF 405 Metres above the sea level to various levels ranging from 380m –340m. Operations stopped in 2008 when the concession agreement between the Federal Government and GILN was terminated.

PRE EXPLOITATION DRILLING

Pre-exploitation drilling continuously needed throughout the life of the mine for the purpose of producing the subsurface geological maps to indicate the layers at the lower benches.

Pre-exploitation drilling needed to confirm tonnage of mineable reserves and for mine planning purposes.

Out of the 3Nos Core drilling Rigs, for Pre-exploitation drilling, 1No is burnt (NIOMCO 431), 1No is unserviceable (scrap). Thus only 1No is presently available.

2Nos additional Core Drilling Rigs (Edeco H40) would be required for full production. Estimated cost of acquisition put at N100 Million.

MINE HAULAGE ROAD, CULVERTS AND DRAINAGES

- Total Mine Road network of Itakpe Mines is 9km
- Estimated 75% of the roads are fully developed while 25% are still under construction
- Average width of the road is 25metres.
- Gradient of road is 7%.
- In view of this, since operations had stopped for about 11years, the mine haulage roads had been washed by rains.
- Drainages are blocked at various points
- Safety berm had been washed away at various points
- 3Nos culverts on the road are in good condition.
- To resume Mine operations, the roads and drainages must be rehabilitated.
- Safety berms have to be rebuilt.

- There is need for the rehabilitation of the mine road, drainages and the safety berm.

MINE LIGHTING

- Mine lighting required for 24hrs operation
- Lighting system along mine haulage road has suffered some deterioration.
- Overhead cable and poles had fallen in some areas.
- About 1000metres of underground armored cables for mine lighting had been removed/missing.

IRON ORE STOCK PILE

- 5NO5 Iron Ore stockpiles established over 3 decades ago.
- The stockpiles designed to be different grades of Iron Ore.
- Over the years, especially during the Concession Agreement, stacking on these stockpiles were done haphazardly. Thus stacking can no longer be said to be based on grades.
- At resumption of Mining Activities, the stockpiled material should be used to blend Run of Mine to ensure acceptable quality at the primary crusher.

WASTE DUMPS

- 3No. Waste Dumps located at MG, M2G and at East pit and at south of west pit mines.
- South Waste Dump for mining operations in the west pit is not currently being used as mining operations are in the east pit.
- Waste Dump at MG abandoned about 25 years ago when it was discovered that a reasonable tonnage of Iron Ore was in-situ below the waste Dump platform.
- The M2G waste dump currently in use is within the pit limit of the Mine,
- To solve this problem, a new waste dump site should be developed not too far from the the present one while ensuring that it is outside the pit-limit and distance from the mine face is minimal.
- Waste already dumped at MG would have to be removed when exploitation of the ore layers gets to the present level of the abandoned waste dump at MG.

MINE SITE OFFICES

- Currently the mine operators and maintenance staff use two porta cabins and one container located near the view point.
- One of the porta cabin is fairly okay, it only requires renovation of the ceiling.
- The other porta cabin is dilapidated with leaking roof, floor with holes, broken doors and not conducive as a site office. It should be scrapped.
- The container is not ventilated. provision should be made to construct windows on the container or install air conditioner.
- There is need to procure 2 additional containers to serve as offices for Engineers and Technicians.

MINE CANTEEN

- There is an existing.
- The canteen is built by placing 2nos forty feet containers together and covering them with a roof.
- The containers are in bad shape with no proper ventilation
- Cooking is done in the open air.
- There is need to rehabilitate the canteen with installation of air conditioners
- A good refrigerator is also needed.
- Refrigerator and air conditioner.

DUST SUPPRESSION IN THE MINE

- Dust is being suppressed by the use of an old 35tonnes Euclid dump trucks was converted to a water sprinkler. The sprinkler is in deplorable condition. The dump truck is weak and cannot convey water up the hill effectively.
- It is highly recommended that 2nos of water sprinkler (Mercedes MB2031 truck with capacity) should be procured at estimated price of 75million to effectively suppress the dust in the mines.

QUARRY

- NIOMCO has a granite quarry outside the perimeter fencing of NIOMCO's headquarters.
- The granite quarry was abandoned over 25 years ago in order to avoid crossing the the (Itakpe-Eika road which has been dualized recently) road with off high Heavy Earth Moving mining equipment.
- NIOMCO has since then been sourcing granite from the Itakpe mine.
- It is recommended that the quarry should remain closed until a new crushing plant can be procured and installed near the deposit and a workshop to repair the equipment is also established near the quarry.

AJABANOKO IRON ORE DEPOSIT

- Ajabanoko has a geological reserve of 60million metric tonnes of iron ore.
- Development of access roads to the deposit which began many years ago is about 50% complete
- Production from the deposit is yet to start.

NIOMCO MINING TITLES

- NIOMCO has a mining lease covering an area of 6.4km² on Itakpe deposit an area of 6.4km² on Itakpe deposit for a period of 25years effective from 14/11/2007.
- Niomco has a mining lease covering an area of 5km² on Ajabanoko deposit for a period of 25years effective from 14/11/2007.

EXPLOSIVE MAGAZINES

- NIOMCO has 4 Nos explosive magazines
- Currently 3nos are in use viz: High explosive magazine, low explosive magazine and detonator magazine.
- The High Explosive Magazine
 - A steel container internally lined with treated planks.
 - Located at about 600m behind the main stores.
 - Capacity is 20 metric tonnes of High explosives.
 - Surrounded by sand embankment, a wire fence and a gate.
 - The gate and parts of the fence are presently broken.
 - Illumination is poor.
 - Security post is made with roofing zinc.

THE LOW EXPLOSIVE MAGAZINE

- Located at pilot mine at the far end of of the East pit.
- These are 3nos, 20ft containers lined with wooden plank which accommodate about 60metric tonnes of low explosives (Ammonium Nitrate).

THE DETONATOR MAGAZINE

- Located about 1km from MD/CEO's office.
- A steel container mounted on tyres and surrounded with wire fence.
- Items stored in the magazine includes all explosive accessories i.e. safety fuses, detonating caps, delay relays, etc.
- Blasting certificate for blasters to be renewed.
- 3 explosive magazine namely for High explosive magazine, Detonating magazine and ANFO magazine to be renewed.

45 METRIC TONNES MAGAZINE

- The 4th magazine under construction since the 80's fell within the right of way of Lokoja – Benin express way
- Another magazine has to be built in another location.

STOCK LEVEL OF EXPLOSIVE AS AT NOVEMBER, 2019**CONSUMMABLES****Explosives and Blasting**

The under listed stocks were transferred to Obajana cement company's explosive magazine for safe keeping as directed by the appropriate authority since December 2010.

The transferred stocks are:

- | | | |
|----|----------------------|-------|
| i. | Detonator (Nonel) | |
| | 15.0m handimaster | 22pcs |
| | 15.0m Dynashoc No 2 | 1pcs |
| | 15.0m Dynashoc No 20 | 27pcs |

| | |
|--------------------------|--------|
| 6.0m DTH | 392pcs |
| 5.0m Electric | 5pcs |
| 5.0m 1.8 copper wire IES | 10pcs |
| Total | 394pcs |

| | | |
|------|-------------------------|---------|
| ii. | Nonel Connectors | |
| | 6.0m Benchmaster | 100pcs |
| | 3.0m Benchmaster | 961pcs |
| | Total | 1061pcs |
| iii. | 75 ms trunkline delays | 2pcs |
| iv. | 25 ms cord delay relays | 877pcs |
| v. | Detonator cap #8 | 1594pcs |
| vi. | Safety fuse | 905m |

Required explosives and blasting accessories for two years uninterrupted operation.
The following estimate is based on the following:

- FACTS
- Itakpe Mine Operation has only 20% of fleet of equipment require to produce
- The capacity of the crushing plant is 2000 metric tonnes per hour
- The stripping ratio of waste to ore is 4:1
- ASSUMPTIONS
- The mine will operate at 20% capacity
- 300 production days per annum
- 3 shift, four Bridgade
- The cycle time to primary crusher and waste dump are 30mins and 10mins respectively.
- With 20% fleet, target set at 1.2million metric tonnes of Ore and 4.8million of waste per annum.

Two years explosives requirement is as shown

| S/NO | ITEMS | QTY |
|------|------------------|----------|
| 1 | High Explosive | 85.6Mt |
| 2 | Ammonium Nitrate | 428Mt |
| 3 | Nonnel Detonator | 6,000pcs |
| 4 | Nonnel Connector | 6,000pcs |
| 5 | Prima Cord | 10,000m |
| 6 | Detonating cap | 150pcs |
| 7 | Safety fuse | 250m |

To produce at full capacity i.e. 2000T/hr, the estimate above should be multiplied by 5.

6.0 PRESENT STATUS OF NIOMCO UNITS ARE AS SHOWN IN THE TABLE BELOW

Below is the present status/work to be carried out to put back the equipment to functional state in the mines.

A. MINES OPERATION STATUS OF THE MINING EQUIPMENT

| S/NO | Equipment | Works to be Done |
|------|---------------------|--|
| 1 | Bulldozer D9R (015) | <ul style="list-style-type: none"> i. Replace worn out rollers, idlers and tracks. ii. Replace Ground Engagement Tools iii. Overhauling of all Hydraulic Cylinders. iv. Carry out 2000hrs servicing. v. Provide batteries and 1000 litres of diesel for test running. vi. Overhauling of Injection Pump and Fuel System. vii. Replacement of Exhaust Mufflers and Claddings |
| 2 | Bulldozer D9N (011) | <ul style="list-style-type: none"> i. Replace worn out tracks group, replace track rollers, segments and idlers. ii. Replace Ground Engagement Tools iii. Overhauling of all Hydraulic Cylinders iv. Carry out 2000hrs servicing. v. Repair operator's seat. vi. Replace batteries and provide 1000litres of diesel for test running. vii. Overhauling of Injection Pump and Fuel System. viii. Replacement of Exhaust Mufflers and Claddings |
| 3 | Bulldozer D9L (006) | <ul style="list-style-type: none"> i. Replace muffler, exhaust pipes and Claddings. ii. Steam clean radiator, overhaul track adjuster and valves. iii. Repair operator's seat and rear view mirrors. iv. Replace track rollers and tracks. v. Carry out 1000hrs servicing. vi. Replace batteries and provide 1000litres of diesel for test running. vii. Overhauling of Injection Pump and Fuel System. |
| 4 | Dozer Cat D8K(005) | <p>Replace injector and priming pumps. Replace final drive duo cone seals. Re-kit all hydraulic cylinders. Replace leaking/worn out hoses. Replace bad switches and gauges. Replace alternator and starter motor. Replace fan and alternator belt. Replace ground engaging tools. Tune up engine. Replace batteries. Overhaul Injection Pump and Fuel Line. Replace Exhaust Mufflers, pipes and Cladding. Repair operator seat. Replace bad/damaged wire harnesses. Carry out 2000hrs servicing and provide 1000litres of diesel for test running.</p> |
| 5 | Cat D9N Dozer (012) | <ul style="list-style-type: none"> (a) Carry out under carriage rebuilt. i.e. replace rollers, idlers segment and tracks (b) Replace Exhaust muffler and claddings. (c) Replace ground engaging tools (d) Carry out 2000hrs servicing (e) Re-kiting of all hydraulic cylinders and water pump. |

| | | |
|----|---|---|
| | | <ul style="list-style-type: none"> (f) Provide batteries (200AH) and 1000liters of diesel for running. (g) Replace operator's seat & mirrors. (h) Overhaul Injection Pump and Fuel Lines. |
| 6 | Cat 5090B face shovel | <ul style="list-style-type: none"> (a) Replacement of joy stick. (b) Re-kiting of all hydraulic cylinders (c) Replacement of AC Compressor. (d) Replacement of alternators and fan belts. (e) Replacement of vehicle inspection device system panel. (f) Repair fuel system (g) Carry out 2000hrs service. (h) Provide batteries (200AH) and 1000liters of diesel. (i) Replace worn out hoses. (j) Replace damaged shift control hood. (k) Replace bucket tips (l) Troubleshoot Engine problems with ET and rectify. (m) Replace all hydraulic hoses |
| 7 | Cat 824G (014) wheel dozer. | <ul style="list-style-type: none"> (a) Repair/replace water pump (b) Replace cutting edges & end bit, Exhaust Mufflers, pipes and Claddings. (c) Rekit all hydraulic cylinders (d) Replace 4 Nos tyres (e) Replace mirrors. (f) Carry out 2000hrs servicing. (g) Provide batteries (200AH) and 1000litres for test running. (i) Overhaul Injection Pump and Fuel Lines. |
| 8 | Terex O & K RH40 (HS-01) (Face Shovel) | <p>Replace radiator and damaged fan blade. Repair engine cover panels. Replace batteries. Replace worn out bucket tips and adapters.</p> <p>Replace worn out hoses. Rekit leaking cylinders. Carry out 2000hrs servicing. Provide 1000 litres of diesel for testing. Replace batteries and provide 1000litres of diesel for test running. Overhaul Injection Pump an Fuel System</p> |
| 9 | Payloader Cat 992C (112) | <ul style="list-style-type: none"> i. Overhaul Transmission System. ii. Overhaul all hydraulic cylinders. iii. Vulcanise tyres, Replace Bucket Tips and pins. iv. Overhaul air conditioning system. v. Replace Exhaust Mufflers, pipes and Cladding. vi. Tune up engine vii. Carry out 2000hrs servicing viii. Replace batteries and provide 1000litres of diesel for test running. ix. Overhaul Injection Pump an Fuel System. |
| 10 | Payloader Cat992C(113) Loader | <p>Overhaul transmission, re-kit hydraulic cylinders, replace leaking/worn out hoses. Replace batteries, carry out 2000hrs servicing, provide 1000 litres of diesel for testing. Replace bucket tips. Repair Air Conditioning system. Overhaul Injection Pump and Fuel Line. Replace Exhaust Mufflers, pipes and Cladding.</p> |

| | | |
|----|---------------------------------|---|
| 11 | Payloader 966F (115) | <ul style="list-style-type: none"> i. Re-kit all hydraulic cylinders, ii. Repair parking brake. iii. Carry out 2000hrs servicing. iv. Replace 4 NOS Tyres. v. Overhaul the Injection Pump and Fuel System. vi. Tune up Engine. vii. Repair Operator's Seat. viii. Check and Repair The Electrical System. ix. Replace Bucket Cutting Edge and provision for spare GET. x. Replace batteries and provide 1000 litres of diesel for test running xi. Replace Exhaust Mufflers, pipes and Cladding. |
| 12 | Payloader 950 (110) | <ul style="list-style-type: none"> i. Overhaul transmission/torque and converter Group. ii. Re-kit all hydraulic cylinders. iii. Replace spider bearing group, repair seat, repair electrical system, replace all damaged gauges and switches. iv. Vulcanise tyres and Replace 4 nos Tyres v. Carry out 2000hrs servicing. vi. Replace batteries and provide 1000 litres of diesel for test running vii. Replace Exhaust Mufflers, pipes and Cladding. viii. Overhaul the Injection Pump and Fuel System. |
| 13 | Loader 980C (108) | <p>Overhaul engine, replace rear duo cone seal and rekit rear brake calipers. Rekit steering, tilt and lift cylinders. Replace rear brake discs and plates and overhaul braking and steering system. Overhaul transmission and torque converter. Overhaul Injection Pump and Fuel Line. Replace Exhaust Mufflers, pipes and Cladding. Replace all leaking and worn out hoses. Replace bad switches, gauges and hour meter. Replace alternator and starter motor. Replace bad wire harnesses. Replace seat.</p> <p>Replace 4Nos tyres. Replace batteries. Carry out 2000hrs servicing and provide 1000 litres of diesel for testing.</p> |
| 14 | Payloader Komatsu WA 800 (WL-1) | <ul style="list-style-type: none"> i. Replace worn out bucket tips and provision for spares. ii. Overhaul Injector pump and Fuel System iii. Top Overhauling of the Engine iv. Repair and Steam clean radiator. v. Overhaul all hydraulic cylinders and replace Hydraulic Hoses. vi. Replace Exhaust Mufflers, pipes and Cladding. vii. Repair/replace 2 Nos starter motors, repair electrical system. viii. Replace horn, backup lamps and side mirrors. ix. Carry out 2000hrs servicing. x. Replace batteries and provide 1000 litres of diesel for test running. |
| 15 | Dump Truck 773E (218) | <ul style="list-style-type: none"> i. Repair dented right side fender. ii. Overhaul Injector pump and Fuel System. iii. Overhaul all hydraulic cylinders and replace Hydraulic Hoses iv. Replace fuel tank cover and vulcanise tyres. v. Replace left side mirror and left door glass winder. |

| | | |
|----|-----------------------------|---|
| | | <ul style="list-style-type: none"> vi. Repair air conditioning system. vii. Replace faulty head lamps and batteries. viii. Replace Exhaust Mufflers, pipes and Cladding ix. Carry out 2000hrs servicing x. Provide 1000 litres of diesel for test running. |
| 16 | Dump Truck 773E (217) | <ul style="list-style-type: none"> I. Replace missing safety pins, replace batteries, provide Electronic Technician (ET) to upgrade all sensors, replace horn switch assembly, reverse alarm switch and also brake lamps. II. Overhaul Injector pump and Fuel System. III. Replace electric door winder. Repair Air conditioning system. Vulcanise tyres. IV. Carry out 2000hrs servicing and replace batteries. V. Re-kit body hoist and steering cylinders. VI. Provide 1000 litres of diesel for test running. VII. Replace Exhaust Mufflers, pipes and Cladding. |
| 17 | Dump Truck 773E (219) | <ul style="list-style-type: none"> i. Re-kit body hoist and steering cylinders. Vulcanise tyres. ii. Replace batteries. iii. Replace left side mirror. iv. Repair air conditioning system. v. Carry out 2000hrs servicing and provide 1000 litres of diesel for test running. vi. Overhaul Injector pump and Fuel System. vii. Replace Exhaust Mufflers, pipes and Cladding. |
| 18 | Cat 773E Dump Truck (216) | <ul style="list-style-type: none"> (a) Replace 6Nos, tyres, 24.00x35. (b) Re-kit body hoist and steering cylinders. (c) Overhaul Injector pump and Fuel System. (d) Replace Exhaust Mufflers, pipes and Cladding (e) Carry out 2000hrs servicing (f) Provide batteries (200AH) and 1000litres for test running. (g) Overhaul rear brakes (h) Repair A/C. |
| 19 | Cat 773B Dump truck (211) | <ul style="list-style-type: none"> (a) Rectify fuel injector leakage (b) Replace 6Nos tyres 24.00 x 35. (c) Carry out 2000hrs servicing (d) Rekit all hydraulic cylinders (e) Provide batteries (200AH) and 1000litres of diesel for test running (f) Rekit steering cylinders and replace oil seal for steering pump drive. (g) Replace operator door locking unit. (h) Repair A/C. (i) Provide special tools for injector pump. (j) Overhaul Injector pump and Fuel System. (k) Replace Exhaust Mufflers, pipes and Cladding. |
| 20 | Euclid R60 Dump Truck (214) | <ul style="list-style-type: none"> (a) Replace 6Nos tyres 24.00 x 35. (b) Over-haul transmission system. (c) Re-kit body hoist and steering cylinders. |

| | | |
|----|----------------------------------|---|
| | | <ul style="list-style-type: none"> (d) Carry out 2000hrs servicing (e) Provide batteries (200AH) and 1000litres of diesel for test running. (f) Overhaul Injector Pump and Fuel System. (g) Replace Exhaust Mufflers, pipes and claddings. |
| 21 | Euclid R60 Dump Truck (213) | <ul style="list-style-type: none"> (a) Replace 6Nos tyres 24.00x 35. (b) Replace drive shaft. (c) Replace steering cylinders (d) Replace missing hoses and gauges. (e) Rekit body hoist cylinders (f) Carry out 2000hrs servicing (g) Provide batteries (200AH) and 1000 litres of diesel for test running. (h) Overhaul Injector Pump and Fuel System. (i) Replace Exhaust Mufflers, pipes and claddings. |
| 22 | Euclid R35 (210) Water Sprinkler | Tune up Engine. Replace radiator hoses. Replace brake valves and repair braking system. Rekit steering cylinders. Rectify leakages on transmission and rear wheel final drive. Replace alternator belt, wiper and horn. Replace batteries. Carry out 2000hrs servicing. Provide 1000 litres of diesel for testing. Overhaul Injector Pump And Fuel System. Replace Exhaust Mufflers, pipes and claddings. Overhaul all suspensions. |
| 23 | Terex (3308) Dumper (215) | <ul style="list-style-type: none"> (a) Replace 6Nos, 21.00 x 35 tyres. (b) Repair leakage of brake system. (c) Rekit body hoist and steering cylinders. (d) Replace PTO oil seal (e) Rekit/repair suspension cylinders. (f) Carry out 2000hrs servicing. (g) Provide batteries (200AH) and 1000litres of diesel for test running. (h) Replace rear duo cone seal and rekit rear brake calipers. (i) Replace Electronic Control Module (ECM). (j) Replace both side door glasses and mirrors. (k) Overhaul Injector Pump and Fuel System. (l) Replace Exhaust Mufflers, pipes and claddings. |
| 24 | Dump Truck Terex 100 (DU1) | <ul style="list-style-type: none"> i. Replace side mirrors. ii. Replace batteries. iii. Carry out 2000hrs servicing and provide 1000litres of diesel for test running. iv. Overhaul Injection Pump and Fuel System. v. Replace Exhaust Mufflers, pipes and Claddings. vi. Rekit/repair suspension cylinders. |

| | | |
|----|-----------------------------|--|
| 25 | Motor Grader 14H (304) | <ul style="list-style-type: none"> i. Repair/Replace exhaust ejector. ii. Replace/repair upper radiator. iii. Replace ripper tips, shank and pin. iv. Replace cutting edge and end bits. v. Repair parking brake. vi. Replace 3 Nos flood lamp and horn assy. vii. Replace reverse alarm. viii. Replace batteries and carry out 2000hrs servicing and provide 1000litres of diesel for test running. ix. Overhaul Injection Pump and Fuel System. x. Replace Exhaust Mufflers and Claddings. |
| 26 | Blast Hole Drill (BHD 01) | <ul style="list-style-type: none"> i. Repair 1 No door catcher. ii. Replace batteries, carry out 2000hrs servicing and provide 1000litres of diesel for test running. iii. Overhaul Injection Pump and Fuel System. iv. Replace Exhaust Muffler and Cladding. |
| 27 | Blast Hole Drill (BHD 02) | <ul style="list-style-type: none"> i. Repair 1 No door catcher. ii. Replace batteries. iii. Carry out 1000hrs servicing and provide 1000litres of diesel for test running. iv. Overhaul Injection Pump and Fuel System. v. Replace Exhaust Muffler and Cladding. |
| 28 | BHD03 (Rock Drill) | <ul style="list-style-type: none"> i. Replace Electronic Control Module. Replace batteries, repair door lock. Carry out 2000hrs servicing. ii. Provide 1000 litres of diesel for testing. iii. Overhaul Injection Pump and Fuel System. iv. Replace Exhaust Muffler and Cladding. |
| 29 | Roc 404A (432) (Rock Drill) | <p>Replace all air hoses. Service control valves. Rekit hydraulic cylinders. Replace Leaking hydraulic hoses. Lubricate machine. Procure 1No DTH hammer (COP 42) for machine. Overhaul Injection Pump and Fuel System.</p> <p>Replace Exhaust Muffler and Cladding.</p> |
| 30 | XR 350 (423) Compressor | <p>Overhaul Engine. Replace fuel lines. Replace push button, circuit breaker and tachometer. Replace bad relays and cable harnesses. Replace 4 Tyres. Replace batteries. Carry out 2000hrs servicing. Provide 1000 litres of diesel for testing. Overhaul Injection Pump and Fuel System.</p> <p>Replace Exhaust Muffler and Cladding.</p> |

B. ASSOCIATED FACILITIES

| S/N o. | Equipment | Works to be Done |
|-----------|---|--|
| 1 | Bendini Crane | <ul style="list-style-type: none"> i. Overhaul engine, replace broken operator's cabin roof glass, replace 2 Nos tyres, batteries and replace sling wire. ii. Carry out 2000hrs servicing. iii. Provide 1000litres of diesel for test running. |
| 2 | Manitou Tyre Handler | <ul style="list-style-type: none"> i. Replace fan belt, overhaul transmission, re-kit hydraulic and steering cylinders, replace right side head lamp, replace missing mirrors, repair operator's seat, overhaul engine, replace batteries. ii. Provide 1000litres of diesel for test running |
| 3 | Manitou Forklift | <ul style="list-style-type: none"> i. Replace fan belt, overhaul engine, overhaul transmission, replace batteries. ii. Re-kit all hydraulic & steering cylinders. Provide 1000litres of diesel for test running. |
| 4 | Personnel Carrier Manitou | Replace kickstarter, alternator, batteries, electronic card. Carry out 2000hrs servicing and provide 1000ltrs of diesel for test running. |
| 5 | Workshops' Tools and rehabilitation works for Mines and Auto workshops. | Replacement of Aluminium Long Span and Cladding for mine main workshop and rehabilitation works of auto workshop. Procure workshop tools and equipment. |
| 6 | Consumables spare parts, Lubricants and Tyres. | Procure Spare Parts for Mining Equipment. Procure Lubricants and Filters for Scheduled Maintenance. Procure Tyres for running Equipment. |

MINES (CONTD')

| S/N | EQUIPMENT/DESCRIPTION OF ITEM | PART NO/MAKE | QT Y | CONDITION AS AT NOV 2019 | LOCATION | REMARKS |
|-----|--|--------------------------------------|---------|-----------------------------|-------------------|---|
| A | QUALITY CONTROL LAB | | | | | |
| 1 | FUME CUPBOARD | FUME HOOD EXHAUST FAN TYPE | 3 | ALL FAULTY | LAB | MODERN REQUIRED |
| 2 | MUFFLE FURNACE | TYPIOH-85TR | 1 | FAULTY | TO DSC BY GILN | NEW ONES REQUIRED |
| 3 | HOT PLATES | | 4 | FAULTY | LAB | NEW ONES REQUIRED |
| 4 | TOP LOADING BALANCE | METTLER- (READABILITY 0.0001G) | 1 | FAULTY | STORE | NEED REPLACEMENT |
| 5 | WATER DISTILLATION EQUIPMENT | MANESTEY | 1 | FAULTY | STORE | MODERN DISTILLATION EQUIPMENT REQUIRED |
| 6 | LAB CHEMICALS | | | EXPIRED | LAB | NEW CHEMICALS REQUIRED |
| 7 | ANALYTICAL BALANCE | METTLER SAUTER | 1 | REQUIRED SERVICE | | SERVICE & CALIBRATION |
| 8 | PYE UNICAM ATOMIC ABSORPTION SPECTROPHOTOMETER | SP9 | 1 | FAULTY | STORE | NEW ONES REQUIRED |
| 9 | PYE UNICAM ATOMIC ABSORPTION SPECTROPHOTOMETER | PU 8650 U | 1 | FAULTY | STORE | NEW ONES REQUIRED |

| 10 | WEMCO FLOTATION | | 1 | NOT INSTALLED | LAB (ELECT MOTOR IN THE STORE) | ELECT MOTOR IN THE STORE |
|----------|--|-------------------|---|-----------------------------|--------------------------------|---|
| 11 | PH METER | | 1 | FAULTY | STORE | |
| 12 | DRYING OVEN | | 3 | FAULTY, | LAB | NEW ONES REQUIRED |
| | | | 1 | OKAY | LAB | NEEDS SERVICING |
| 13 | MORTAR MILL | | 1 | OKAY | LAB | NEEDS SERVICING |
| 14 | DENVER ROD MILL | | 1 | OKAY | LAB | ELECT MOTOR IN STORE |
| 15 | POLISHING MACHINE | | 1 | OKAY | STORE | NOT INSTALLED |
| 16 | CUTTING/LAPPING MACHINE | | 1 | NOT FUNCTIONING | STORE | FAULTY CONTROL SWITCH, |
| 17 | CUTTING MACHINE | | 1 | NOT INSTALLED | LAB | |
| 18 | POLARIZED MICROSCOPE | | 1 | NOT INSTALLED | STORE | OKAY |
| 19 | BINOCULAR MICROSCOPE | | 2 | FUNCTIONING | STORE | OKAY |
| 20 | U.V. VISIBLE SPECTROPHOTOMETER | PERKIN ELMER | 1 | NOT FUNCTIONING | STORE | REPLACE |
| 21 | SCREENING/SIEVING MACHINE | | 1 | INSTALLED | STORE | ELECTRT. MOTOR |
| B | SURVEY DEPARTMENT | | | | | |
| 1 | KERNSWISS THEODOLITE | DKM2-AE | 1 | BAD | STORE | Require replacement with latest verslon |
| 2 | TRIPOD | THEODOLITE TRIPOD | 2 | BAD | STORE | TO BE REPLACED |
| 3 | TRIPOD | LEVEL TRIPOD | 2 | BAD | | TO BE REPLACED |
| 4 | STAFF | LEVELLING STAFF | 3 | 3 ARE NOT IN GOOD CONDITION | | TO BE REPLACED |
| C | MINE GEOLOGY/MINE QUALITY CONTROL | | | | | |

| 1 | CORE DRILLING RIG FOR SUBSURFACE MAPPING | EDECO, (NON WIRE LINE TYPE) | 1 | BAD | M2G | To be replaced with more current version |
|----------|--|-----------------------------|---|---|-------------------|--|
| | Jaw crusher | Crushes from 40mm to 10mm | 1 | Not in good condition | Bergeaud plant | Overhaul: inspection, repair, service |
| | Dual roll crusher | Crushes from 10mm to 1mm | 1 | Not in good condition | Bergeaud plant | |
| | Rotap sieve shakers | Ranges | 1 | Not in good condition | Bergeaud plant | Electric motor missing |
| | Riffle Spitter (jones) | 040G -022 | 1 | Good condition | Bergeaud plant | okay |
| D | BLASTING AND EXPLOSIVE UNIT | | | | | |
| 1 | High EXPLOSIVE MAGAZINE | 45T | 1 | DESTROYED BY THE ONGOING LOKOJA-BENIN ROAD CONSTRUCTION | | TO BE REPLACED |
| 2 | STEEL CONTAINER H.E. MAGAZINE | 20T | 1 | OK | BEHIND MAIN STORE | VANDALIZED |
| 3 | STEEL CONTAINER ANFO MAGAZINE | 40T | 2 | FAIRLY OK | PILOT MINE | TEMPORARY MAGAZINE |
| 4 | STEEL CONTAINER (BLASTING ACCESSORIES) | | 1 | OK | SITE | VANDALIZED |
| E | MINES OPERATION | | | | | |
| 1 | PORTER CABIN | FIELD OFFICES | 3 | BAD | | NEW TO BE CONSTRUCTED |
| 2 | CANTEEN | MINE SITE | 1 | BAD | | |
| 3 | WALKIE TALKIE | 10 KM RADIUS COVERAGE | 8 | BAD | | |
| 4 | WALKIE TALKIE CHARGERS | ELECTRICALS | 8 | BAD | | |
| F | BERGEAUD PLANT | | | | | |
| 1 | HOPPER | | | OK | | CLEAN |

| | | | | | |
|---|-------------------|--|--|----------|---------|
| 2 | JAW CRUSHER | | | OK | OK |
| 3 | POWER CABLE | | | MISSING | REPLACE |
| 4 | CONVEYOR BELT | | | EXPIRED | REPLACE |
| 5 | IDLE ROLLERS | | | BAD | REPLACE |
| 6 | RETURNING ROLLERS | | | BAD | REPLACE |
| 7 | MESH | | | CORRODED | REPLACE |
| 8 | BELTS | | | BAD | REPLACE |
| 9 | CONE CRUSHER | | | OK | SERVICE |

CARTOGRAPHY SECTIONS

The existing equipment are obsolete in bad conditions and need total overhauling and replacement with modern equipment to give room for transformation from analog to digital methods of producing maps

TRANSFORMATION OF MAP MAKING PROCESS FROM ANALOG TO DIGITAL METHOD

The following items will be required for the transformation processes:

| NO | DESCRIPTION | QUANTITY |
|----|--|----------|
| 1 | Laptop(core i5HP pavilion 12GB ram 500GB hdd) | 4 |
| 2 | HP design jet plotter T520 | 1 |
| 3 | HP office jet 8720 A3 printer | 1 |
| 4 | Global Positioning System(GPS) GARMIN GPS MAP 276CX Model | 3 |
| 5 | Sharp AR6020 digital multifunction A3 Photocopier | 1 |
| 6 | HP Scanjet flatbed | 1 |
| 7 | Software(Non licensed) A: ARCGIS B: AUTOCAD | 1 1 |

C BENEFICIATION PLANT

| S/N | EQUIPMENT/UNITS | STATUS | REMARK |
|-----|---|---|--|
| 1 | PRIMARY CRUSHER Gyratory Crusher 54" x 74" Capacity: 2000tph Make: Allis Minerals Systems Emmisa. | Dismantled | Reassembling and reactivation of the crusher including the replacement of the worn out sleeve, spider bushing, main shaft, eccentric gear, liners, v-belts, dust seal, bolts and servicing of parts. |
| 2 | CONVEYOR BELTS | All conveyor belts of various sizes for the transportation of materials expired due to year of manufacture. | To be replaced |
| 3 | BELT CONVEYORS | Carriage and Return rollers, scraper blades, hoses, liners, drum lagging bad | To be relagged/replaced. |
| 4 | SECONDARY CRUSHER <i>Type</i> - Jaw 1080 <i>Size</i> - 1020 x 800 mm <i>Capacity</i> - 2000tph | Screen dismantled, expired v-belts, worn out eccentric gear, bearing and seal bad, lining worn out. | To be rehabilitated and reassembled |
| 5 | TRANSFER STATIONS | Pump and chute needs overhauling | To be overhauled, re-lined/ repaired. |
| 6 | STACKER 1 Capacity: 2275tph Travel speed - 8 m/min to 16 m/min Max.travel length - 420 m Total no. of wheels- 24 Drive motor - 10x 7.5 kW | Drive bearings, disc brake, winch in good condition. Lubrication system not okay, hoisting and slewing slings bad | To be serviced/repared |
| 7 | RECLAIMER Travel speed -1.5 m/min to 15 m/min Max. travel length - 400 m Total no. of wheels - 32 Drive motor - 16x 5.5 kW | Bucket mechanism, drive & bearing, brakes in good condition. Buckets, adapters, carriage guide wheels, beam frame, rake are in bad condition. Conveyor hoppers, scraper blades, chutes liners bad. | To be replaced, serviced and repaired. |
| 8 | TRANSFER CAR | Rail buckled | To be repaired |
| 9 | REPARTITION BIN | Concrete beams sectionally shattered, liners damaged, bin jammed. | To be reactivated, cleared and relined. |

| | | | |
|----|---|---|--|
| 10 | AG MILLS (1, 2, & 3) Type - Wet grate discharge Size - 20'Ø x 10' L Drive motor - 2700kW Capacity- 292 ± 10% | Liners, lifters, trommel screen panels, chute liners worn out, mechanical winch bad, motorized valves faulty. | To be serviced/ parts replaced |
| 11 | Slurry tanks | Tanks, drain valves, water valves, rubber lining, gate valves & Teguflex damaged. | To be relagged, and replaced. |
| 12 | Sump pumps | V-belts expired, pumps consumables damaged | To be replaced and repaired |
| 13 | Wet Screens | All screen panels worn out, water spraying system faulty, v-belt expired, Wet Screen panel removed. | To be reactivated and panels changed from iron to polyurethane or upgraded to modern system. |
| 14 | Warman pumps | Pump components rusted, worn out, damaged, v-belt expired, gate valves damaged. | To be repaired/serviced and replaced. |
| 15 | FLOCCULANT STATION | All piping system bad, station to be serviced | All piping system to be replaced, station to be serviced. |
| 16 | Cyclones | Trellex hoses damaged, pressure gauge faulty. | Hoses to be replaced and pressure gauges replaced. |
| 17 | Filter Beds | One gear box faulty, Filter cloth, water spray, scrappers, tensioning device, hydraulic jacks, tank liners, gauges & meters, Belt stripe bad. | To be replaced and repaired |
| 18 | FILTRATE PUMPS | All filtrate pumps are bad, not in working condition. | To be replaced |
| 19 | VACUUM PUMPS | Pressure relief valve solenoids faulty, 2 No. pumps bad, v-belt expired | To be repaired/replaced. |
| 20 | V-Belts | All V-belt expired | To be replaced |
| 21 | THICKENER Ø60m | Wheel track damaged, rake wheels, drives, sump pump, and suction valve bad. V-belt expired. | To be resurfaced, serviced/ repaired |
| 22 | Benef Plant Laboratory Equipment | ASOMA machine, electric oven, disc mill, vibrator, sieves, plastic flask bad. IQSpectro Analyser yet to be installed | To be repaired/serviced and Analyser to be installed and personnel trained. |

| | | | |
|----|---------------------|--|--|
| 23 | Osara Dam | Pump couplings, shaft, seals, gland packing, impeller, overheating of pump | To be rehabilitated |
| 24 | Overhead tank | High sedimentation of mud, tank deteriorating. | Mud to be cleared and tank to be repainted |
| 25 | Fire Fighting Truck | Old and obsolete. | To be rehabilitated/New one procured |
| 26 | Working Tools | | To be procured |

D. SUPERCONCENTRATE (SCP) AND WEATHERED ORE PRE-TREATMENT PLANT (WOTP)

| S/NO | WORK TO BE DONE | WORK DONE | % COMPLETION |
|------|--|--|--------------|
| 1 | Spare parts and consumables for test running of SCP | Spare parts and consumables for test running of SCP+ WOTP | 90 |
| 2 | Audit of Steel Work, Mechanical and Process to determine present status after six years of stoppage of installation. | Audit of Steel Work, Mechanical and Process to determine present status after six years of stoppage of installation. | 100 |
| 3 | Audit of Electrical and automation equipment after six years of installation and non-use. | Audit of Electrical and automation equipment after six years of installation and non-use. | 100 |
| 4 | Remobilization of key expatriate and Nigerian personnel | Remobilization of key expatriate and Nigerian personnel | 100 |
| 5 | Reimbursement of the cost of replacing expired parts of the equipment | Reimbursement of the cost of replacing expired parts of the equipment | 100 |
| 6 | Support facilities for ancillary sub-station | Support facilities for ancillary sub-station | 75 |
| 7 | Additional equipment for concentrate industrial plant | Weathered ore pretreatment equipment | 90 |
| 8 | Additional set of documentation to be provided to NIOMCO | Not yet done | 0 |
| 9 | Sourcing, importation and remobilization of heavy equipment for the erection work and consumables for commissioning | Sourcing, importation and remobilization of heavy equipment for the erection work and consumables for commissioning | 90 |

E. ELECTRICAL SECTION (POWER AND UTILITIES)

| S/N | EQUIPMENT NAME | SPECIFICATION | UOM | QTY | Status as at Nov 2019 | Remarks/Responsibility |
|-----|------------------------------|---|-----|-----|-----------------------|------------------------|
| 1 | BERGEAUD PLANT | | | | | |
| 1a | Switchboard Panel | incommer feeder C.B 400A | Nos | 1 | Bad | To be Procured |
| 1b | Switchboard Panel | MCCB,250AMP,4Pole | Nos | 1 | Bad | To be Procured |
| 1c | Changeover switch | 400Amp,415v,4P,3 position,centre zero | Nos | 1 | Bad | To be Procured |
| 2 | WEST PIT | | | | | |
| 2a | ACB (Breaker) | 800AMP,415v,4p,make-ALSTOM | Nos | 1 | Bad | Needs Replacement |
| 2b | Outgoing feeder(MCCB) | 63AMP,3P,415V,make ALSTOM | Nos | 6 | Bad | To be Replaced |
| 3 | EAST PIT | | | | | |
| 3a | Battery with Battery charger | 12v,65Ah, Lead Acid Cell | Nos | 10 | Bad | To be replaced |
| 3b | mobile Tower light Genset | 13KVA,415v | Nos | 1 | fairly Good | Overhauling Required |
| 4 | PRIMARY CRUSHER | | | | | |
| 4a | ALTIVAR | 37 KW-50HP -ALTIVAR 5 | Nos | 1 | Bad | To be Procured |
| 5 | PRIMARY CRUSHER SUBSTATION | | | | | |
| a | Battery charger panel | 110v dc for protection | Nos | 1 | Bad | To be repaired |
| b | Battery bank | 12V,75Ah, Lead Acid Cell | Nos | 10 | Bad | To be Procured |
| 6.a | 132 KV SUBSTATION | | | | | |
| 6.b | CB22,R-Y-B | Tripping and closing coils | Nos | 3 | Bad | To be Procured |
| 6.c | CB22,R-Y-B | spring charging mechanism | Nos | 3 | Bad | To be Procured |
| 6.d | CB22,R-Y-B | charging motor | Nos | 3 | Bad | To be Procured |
| 6.e | MPT41 TRANSFORMER | Tap changer remote operation to be put in service | Nos | 1 | Bad | For servicing |

| 6.f | MPT31/41 TRANSFORMER | Hlgh Voltage outdoor Live Tank, 1250A, 3phase mounted sf6 circuit breaker, 145KV | Nos | 2 | Bad | To be replaced | | | |
|-----|--------------------------|--|-----|-----|-----|-----------------|--|--|--|
| 6.g | MPT 31 | Tap changer operation to be put in service | Nos | | Bad | To be purchased | | | |
| 6.h | CB12 R-Y-B | spring charging mechanism | Nos | 3 | Bad | To be repaired | | | |
| 6.i | CB12 R-Y-B | Spring charging motor | Nos | 3 | Bad | To be repaired | | | |
| 6.j | CB51 ABB | charging mechanism | Nos | 1 | bad | To be purchased | | | |
| 6.k | 132KVA MAIN S/S | AC.Voltage power transducer | Nos | 10 | Bad | To be purchased | | | |
| 6.l | 132KVA MAIN S/S | AC current transducer | Nos | 10 | Bad | To be purchased | | | |
| 6.m | Lead acid batteries | 100Ah, 12V | Nos | 10 | Bad | To be purchased | | | |
| 6.n | Indicator lamp | 10W, 110VD.C | Nos | 500 | Bad | To be replaced | | | |
| 6.o | Analog Pointer.Voltmeter | 132kv/100V | Nos | 6 | Bad | To be purchased | | | |
| 6.p | Analog Ammeter | | | 10 | Bad | To be procured | | | |
| 6.r | 11KV MAIN SUBSTATION | 132kv Synchronizing check, RVKS 332, Relay | Nos | 5 | Bad | To be procured | | | |
| 6.s | 11KV MAIN SUBSTATION | 239 motor protection relay | Nos | 10 | Bad | To be procured | | | |
| 6.t | 11KV MAIN SUBSTATION | 11kv measuring Panel control card | Nos | 2 | Bad | To be Procured | | | |
| 6.u | 11KV MAIN SUBSTATION | Capacitor bank control | Nos | 1 | Bad | To be Procured | | | |
| 6.v | N12AD01 | Repair of panel | Nos | 1 | Bad | To be repaired | | | |
| 7 | Sub - Station (N12 AD01) | | | | | | | | |
| 7.a | measurement panel | 101 measuring panel(control panel) | Nos | 1 | bad | To be procured | | | |
| 7.b | outgoing feeders | 11kv,630AMP Sfe indoor switch gear, 3pole | Nos | 10 | bad | To Be replaced | | | |
| 7.c | outgoing feeders | No-112, 11kv grinding mill supply | Nos | 1 | bad | To be procured | | | |
| 7.d | indicating lamps | 110v DC | Nos | 100 | bad | To be Procured | | | |
| 7.e | protection relays | 2246D75100 | Nos | 100 | bad | To be purchased | | | |
| 7.f | protection relays | 2248E75100 | Nos | 50 | bad | To be purchased | | | |

| | | | | | | | |
|-----|-------------------------------------|---|------------------------|------|----|-------------------|-----------------|
| 7.g | overcurrent+overload relay | PAKS3350make France | ENERTEC,Schelumberger- | Nos | 5 | bad | To be purchased |
| 7.h | Earth fault protection relay | PAKS5110make France | ENERTEC,Schelumberger- | Nos | 5 | bad | To be purchased |
| 7.i | Control relay | (TEC) 110V DC 1783471C00 | | Nos | 30 | Bad | To be purchased |
| 7.j | Battery bank | 1.2VX90 NOS, 160AH make | SHAFT Germany | Nos | 10 | bad | To be purchased |
| 7.k | Power factor Control | Capacitor | | Nos | 1 | bad | To be repaired |
| | | | | Nos | 1 | Bad | To be purchased |
| 8 | REMOVAL SUBSTATION | | | | | | |
| 8.a | MCC PANEL D29AC01 | Complete 1250A L.V Electrical Switch gear panel main C.B switch board cabinet | | Nos | 1 | Bad | To be purchased |
| 8.b | Battery bank | Lead Acid battery 12V, 75Ah | | Nos | 10 | bad | To be purchased |
| 8.c | SUBSTATION ROOM | roof damaged- Leakage | | Lots | | to be repaired | To be repaired |
| 8.d | substation room | Provision of copper bus bar 60mmX10mm Copper bar | | mtrs | 30 | Bad | To be purchased |
| 8.e | substation room | 11kV terminating kit (indoor) | | Set | 1 | Bad | To be purchased |
| 8.f | substation room | L.V Jofnting kit 16mm ² -50mm ² | | set | 5 | as spare | To be purchased |
| 8.g | substation room | 11kV terminating kit (outdoor) | | Set | 5 | as spare | To be purchased |
| 8.h | substation room | Bolt and Nut | | Lots | | Not available | To be purchased |
| | TAILINGS DISPOSAL SUBSTATION | | | | | | |
| 9 | D9ZAD01 | Complete 1250A L.V Electrical Switch gear panel main C.B switch board cabinet | | Nos | 1 | Bad | To be procured |
| 9.a | Battery bank | Lead Acid battery 12V, 75Ah | | Nos | 10 | Bad | To be procured |
| 9.b | 800KVA Transformer | New Transformer | | Nos | 1 | not in place | To be procured |

| | substation room | roof damaged & Leakage | Nos | 1 | Bad | To be procured |
|------|-----------------------|---|------|------|---------------|----------------|
| 9.c | | | | | | |
| 9.d | | Provision of copper bus bar 60mmX10mm Copper bar | mtrs | 30 | not in place | To be procured |
| 9.e | | Bolt and Nut | Lots | Lots | Not available | To be procured |
| 9.f | | 11kV Euromold 400LR Elbow connector | Nos | 12 | Bad | To be procured |
| 9.g | | Roof leakage | Lots | Lots | Bad | To be procured |
| 10 | CONVEYOR BELT BC74 | | | | | |
| 10.a | limit switches | | Nos | 4 | Bad | To be procured |
| 11 | SECONDARY CRUSHER | | | | | To be procured |
| 11.a | VVFD | ALTIVAR,45 KW,TELEMECHANIC MAKE | Nos | 1 | not in place | To be procured |
| 12 | EMERGENCY RECLAIMER | | | | | |
| 12.a | Electric motor | 15KW 3phase, conveyor belt motor | Nos | 1 | Bad | To be procured |
| 12.b | RECLAIMER | 11kV male and female socket coupler | Nos | 1 | Bad | To be procured |
| 12.c | Reclaimer | Emergency pull cord contactor | Nos | 10 | Bad | To be procured |
| 13.a | HT power distribution | Motor protection relay,POWER MANAGEMENT 239,MAKE-GENERAL ELECTRIC | Nos | 10 | Bad | To be procured |
| 13.b | Intömmar-2 ACB | 1600AMP,FRAME 1600L,MAKE UNILEC | Nos | 1 | Bad | To be procured |
| 13.c | Battery bank | Lead Acid battery 12V, 100Ah | Nos | 10 | Bad | To be procured |
| 14 | STACKER3+STACKER4 | | | | | |
| 14.a | ALTIVAR | Crawler motor,30kw 400v,make OMRON | Nos | 1 | Bad | To be procured |
| 14.b | ISOLATOR | 11KV 400AMP,Make-GEC ALSTOM | Nos | 1 | Bad | To be procured |
| 15 | STACKER 2 | | | | | |
| 15.a | Travelling motor | ABB MOTOR,5.5kw | Nos | 2 | Bad | To be procured |
| 16a | GRINDING MILL-1 | | | | | |

| | | NIVOSONIC, Make- ENDRESS+HAUSER | Nos | 1 | Bad | To be procured |
|-------|--------------------------------|---|------|----|-----|-----------------|
| 16. b | Bin level sensor | | | 1 | | |
| 18 | GRINDING MILL-3 | | | | | |
| 18a | Belt scale Electronics | Single Load cell make-RAMSEY | Nos | 1 | bad | To be procured |
| 18b | Belt scale Electronics | speed sensors, Make-Ramsey | Nos | 10 | bad | To be procured |
| 18c | Motorised valves | NB300. NB200 NB150, MAKE-L BERNAD | Nos | 6 | Bad | To be procured |
| 18d | proximity switches | sensing distance > 10mm, dia 40mm | Nos | 20 | bad | To be procured |
| 18e | sump pump | 3.7kw, 3 Phase motor | Nos | 1 | bad | To be procured |
| 18f | overhead crane | screen area | Nos | 1 | Bad | To be repaired |
| 18g | push button station | start+stop+emergency stop, make telemechanique | Nos | 20 | bad | To Be replaced |
| 18h | Water proof Push button | Red_Green with cap | Nos | 50 | bad | To be procured |
| 19 | BENEF MAIN CONTROL ROOM | | | | | |
| 19a. | Feeder | Repair of mill feeder panels | Lots | | Bad | To be purchased |
| 20 | BENEF PLANT | | | | | |
| 20.a | Motorised Valve | F18LV03+F28lv03+F38lv03 | Nos | 3 | bad | To be purchased |
| 20.c | Density meters | F17DT01+F17DT02+F17DT03+F17DT04+F17DT05+F27DT01+F27DT02+F27DT03+F27DT04+F27DT05+F37DT01+F37DT02+F37DT03+F37DT04+F37DT05 | Nos | 12 | bad | To be purchased |
| 20. d | Flowmeter | F16FT06+F26FT06+F36FT06(NB150), Rcleaning spirals, Make Enress+Hauser | Nos | 3 | bad | To be purchased |
| 20e | Flowmeter | F15FT04+F25FT04+F35FT04, (NB350) MAKE-ENDRESS+HAUSER, Cleaning spirals | Nos | 3 | bad | To be purchased |
| 20f | Flowmeter | F14FT02+F24FT02+F34FT02, NB350, MAKE-ENDRESS+HAUSER | Nos | 3 | bad | To be purchased |

| | | | | | | |
|------|--------------------------------------|--|-----|-----|-----|-----------------|
| 20g | Flowmeter | F17FT01+F27FT01+F37FT01,NB350,MAKE- ENDRESS+HAUSER | Nos | 3 | bad | To be purchased |
| 20h | Flowmeter | F14FT01+F24FT01+F34FT01,NB150,MAKE- ENDRESS+HAUSER | Nos | 3 | bad | To be purchased |
| 20i | Flowmeter | F16FT07+F26FT07+F36FT07(NB150),MAKE -ENDRESS+HAUSER | Nos | 3 | bad | To be purchased |
| 20j | Electronic card for Motorised valves | LINE-1+LINE2+LINE3, Make L-Bernad | Nos | 15 | bad | To be purchased |
| 20k | VALVE PANEL | G92AC10+G92AC11 | Nos | 2 | bad | To be purchased |
| 21 | FILTRATION | 40W, 120VAC Electra screw type bulb | Nos | 100 | Bad | To be purchased |
| 21.a | Limit switch | G11JSH01,CLOCKNER MOLLER MAKE | Nos | 11 | Bad | To be purchased |
| 21.b | pressure switch | G12PSL06 | Nos | 11 | bad | To be purchased |
| 21.c | Pull cord switch | G12HS04 | Nos | 22 | Bad | To be purchased |
| 21.d | Jack motor limit switches | filter cloth up/down | Nos | 22 | bad | To be purchased |
| 21.e | Filter cloth misalignment switch | filter cloth misalignment | Nos | 22 | Bad | To be purchased |
| 21.f | overhead crane | travelling G71M02,0.3/0.2KW,18A3X25A motor | Nos | 2 | bad | To be repaired |
| 22 | THICKENER | | | | | |
| 22.a | sum pump motor | 5.5kw sump pump with panel | Nos | 2 | bad | To be purchased |
| 22.b | low voltage pumps | 15kw,415v with start stop panel | Nos | 5 | bad | To be purchased |
| 22.c | Density meter | 150mm,make- Dr Birthold | Nos | 3 | bad | To be purchased |
| 22.d | control panel | start stop+Emergency stop | Nos | 1 | bad | To be purchased |
| 22 | control panel | start(2nos) stop(2 Nos)+Emergency stop(2 nos) | Nos | 2 | Bad | To be purchased |
| 24 | LOADING AND STORAGE | | | | | |

| 24.a | SUBSTATION | ISOLATOR FLAUKIT M GEC ALSTHOM MAKE | Nos | 1 | bad | To be purchased |
|------|-----------------------------------|--|------|------|----------------|-----------------|
| 24.c | battery bank | 12V,75Ah Lead acid | Nos | 1 | bad | To be purchased |
| 24.d | roof leakage | roof leakage | Lots | Lots | bad | To be purchased |
| 24.e | ALTIVAR | ALTIVAR 90KW,415v | Nos | 2 | Bad | To be purchased |
| 26.a | Battery bank | 12V,75Ah Lead acid | Nos | 10 | bad | To be purchased |
| 28 | LOADING | | | | | |
| 29 | CONCENTRATE STORAGE YARD | | | | | |
| 30 | STACKER1 | | | | | |
| 30.a | Contactora | Telemecanique CA2.E.Coil voltage 110vAC LC1 EC03 | Nos | 50 | bad | To be purchased |
| 30.c | Pull cord switch | Limit switch Telemecanique make | Nos | 10 | bad | To be purchased |
| 30.f | ALTIVAR | Altivar,Omron make, 5.5kW | Nos | 2 | Bad | To be purchased |
| 31 | RECLAIMER | | | | | |
| 31.a | Emergency stop box | Telemecanique | Nos | 10 | bad | To be purchased |
| 31.b | Disk Brake power supply panel box | 24V DC Power supply D21AA08 | Nos | 3 | Bad | To be repaired |
| 31.c | Main load Breaker | 800AMP, UNILEC MAKE | Nos | 1 | bad | To be purchased |
| 31.d | MCB | 4P,63AMP | Nos | 5 | bad | To be purchased |
| 31.h | ALTIVAR | Altivar 75kW, for bridge conveyor | Nos | 1 | bad | To be purchased |
| 32 | OSARA DAM | | | | | |
| | SUBSTATION PANELS | | | | | |
| 32.a | Load break switch | 11KV LOAD BREAK SWITCH,MAKE-ALSTHOM | Nos | 1 | Design problem | To be procured |

| | | | | | | |
|-------|--------------------------------|---|------|-----|---------------|-----------------|
| 32. b | 6KV Motor protection Relays | Motor protection relay 239 | Nos | 3 | bad | To be purchased |
| 32. d | Low voltage distribution panel | M11AD03 | Nos | 1 | bad | To be purchased |
| 33. d | 11kV Substation | Copper Bar 5x60mm ² | mtrs | 100 | bad | To be procured |
| 34. d | 11kV Substation | Complete Battery charger; 3 phase, 3.63kVA, 110V D.C | No | 1 | Bad | To be replaced |
| | | Complete 800A, 600V L.V Electrical Cubicle switch gear panel with main C.B switchboard cabinet | No | 1 | | To be procured |
| | 11kV Substation | Repair of 11kV, 1600kV transformer | No | 1 | Bad | To be repaired |
| | | PLANT ILLUMINATION | | | | |
| 1 | | Plant illumination with 100W LED, photocell control and contactor | Lot | Lot | Not available | To be procured |
| | | PLANT AIRCONDITIONING | | | | |
| 1 | | 2 ton standing cabinet air-conditioners | Nos | 65 | Bad | To be purchased |
| | | CABLE LUGS WITH VARIOUS SIZES | | | | |
| 1 | | 25mm ² , 35mm ² , 50mm ² , 70mm ² , 95mm ² e.t.c | Lot | Lot | Bad | To be purchased |

| | | | | | | |
|--|----------------------------|--|--|--|--|--|
| | EMERGENCY PULL CORD | | | | | |
| | | | | | | |

| | | | | | | |
|---|-----|---|-----|-----|-----|-----------------|
| 1 | | Pullcord bulb, 110VAC 3W pin type | Nos | 100 | Bad | To be purchased |
| | | | | | | |
| | PLC | | | | | |
| 1 | | Upgrading of PLC network (phase 1) | Lot | Lot | Bad | To be replaced |
| 2 | | Upgrading of PLC network phase 11 and 111 | Lot | Lot | Bad | To be replaced |

| | | | | | | |
|---|-------------------------------------|--|-----|-----|----------|-----------------|
| | TELECOMMUNICATION | | | | | |
| | | upgrading of communication system todigital and wireless voice, video and data for 15km radius for 500 subscribers voip users and internet communication | Lot | Lot | Outdated | |
| 1 | Intercom and internet communication | | | | | |
| 2 | | Beneficiation process - monitoring and NIOMCO security surveillance | | | | |
| 3 | | Mototrolia Walkie-Talkie radio for Mines maintenance and operation | Nos | 60 | | |
| 4 | | Radio Base station (Mines operation) | | | Bad | To be repaired |
| 5 | | Radio Base station (Mines Maintenance) | | | | To be repaired |
| 6 | | Mototrolia Walkie-Talkie radio for beneficiation maintenance and operation | Nos | 50 | Bad | To be purchased |

CABLES FOR BENEFICIATION PLANT OPERATION

| | | | | | |
|---|-----------------------|------|--------|-----|----------------|
| 1 | 2G 1.5mm2 Copper flex | Mtrs | 2,500 | Bad | To be procured |
| 2 | 2G 1.5mm2 Copper flex | Mtrs | 100 | Bad | To be procured |
| 3 | 3G 1mm2 | Mtrs | 1,000 | Bad | To be procured |
| 4 | 3G 1.5mm2 | Mtrs | 14,200 | Bad | To be procured |
| 5 | 3G 2.5mm2 | Mtrs | 500 | Bad | To be procured |
| 6 | 3G 2.5mm2 | Mtrs | 2,000 | Bad | To be procured |

DRAFT COPY

| | | | | | |
|----|---|------|-------|-----|----------------|
| 35 | 12G 2.5mm2 | Mtrs | 3,000 | Bad | To be procured |
| 36 | 19G 1.5mm2 | Mtrs | 2,500 | Bad | To be procured |
| 37 | 24G 1.5mm2 | Mtrs | 1,000 | Bad | To be procured |
| 38 | 24G 2.5mm2 | Mtrs | 2,000 | Bad | To be procured |
| 39 | 20G 1mm2 | Mtrs | 200 | Bad | To be procured |
| 40 | 30G 1mm2 | Mtrs | 200 | Bad | To be procured |
| 41 | 27G 1.5mm2 | Mtrs | 1,000 | Bad | To be procured |
| 42 | 28G 1.5mm2 (cable reel) | Mtrs | 2,000 | Bad | To be procured |
| 43 | 37G 1.5mm2 | Mtrs | 3,000 | Bad | To be procured |
| 44 | 37G 2.5mm2 | Mtrs | 200 | Bad | To be procured |
| 45 | 11kV 3X35mm2 XLPE Cable | Mtrs | 200 | Bad | To be procured |
| 46 | 11kV 3x70mm2 XLPE Cable | Mtrs | 200 | Bad | To be procured |
| 47 | 1x35mm2 bare conductor earth wire 7x6mm2 | Mtrs | 500 | Bad | To be procured |
| 48 | 11kV 3x95mm2 XLPE Cable | Mtrs | 200 | Bad | To be procured |
| 49 | Recline 4x70mm2 Aluminum | Mtrs | 2,000 | Bad | To be procured |
| 50 | L.V 3x150mm2 armoured cable | Mtrs | 200 | Bad | To be procured |
| 51 | L.V 4x10mm2 Copper Cable | Mtrs | 1,000 | Bad | To be procured |
| 52 | L.V 1x300mm2 Aluminum armoured cable | Mtrs | 500 | Bad | To be procured |
| 53 | L.V 1x240mm2 copper cable | Mtrs | 250 | Bad | To be procured |
| 54 | 1x185mm2 Earth Copper Conductor | Mtrs | 200 | Bad | To be procured |
| 55 | 11kV 3x70mm2 +1x95XLPE Cable | Mtrs | 1,000 | Bad | To be procured |

F. TRANSPORT INFRASTRUCTURE**F1. ORE RAIL LINE**

We have 2 functional locomotives for the transportation of concentrate to ASCL which are now presently transferred to the Ministry of Transport. It is recommended we retrieve the two locomotive or procure new ones to enable us transport our product independently.

We have 37 wagons at Itakpe, 12 at Ajaokuta, 22 at Agbor, totaling 71 Nos Gondola wagons.

The marshaling yard at Itakpe and Ajaokuta are still on wooden sleepers which needs to be replaced with to concrete sleepers because the wooden sleepers have degenerated.

F2. JETTY

There is a Jetty at Ajaokuta which was used to transport superconcentrate to Warri Port for Delta Steel Aladja. It is recommended that the Jetty be rehabilitated for alternative transport to Warri.

G. ESTATE INFRASTRUCTURE**VALUATION OF NATIONAL IRON ORE MINING COMPANY'S PROPERTY (BUILDINGS)**

| S/NO. | BUILDING TYPE | DESCRIPTION | NO.OF BLOCK | STATUS | RECOMMENDATION |
|-------|----------------------------|--------------------------------------|-------------|---------------------|----------------------|
| 1 | Medical Centre | Purpose Built Hospital Accommodation | 3 | In a good condition | |
| 2 | Hall | Multipurpose Hall | 1 | In a fair condition | Needs renovation |
| 3 | Canteen | Senior Staff Canteen | 1 | Fair | " " |
| 4 | Workshop/Office | Estate Camp Maintenance Workshop | 2 | Fair | Needs Reconstruction |
| 5 | Store | Civil Store | 1 | Fair | Needs Renovation |
| 6 | Bank | Banking Services | 1 | Fair | " " |
| 7 | Bank | Banking Services | 1 | Fair | " " |
| 8 | Sofremines Club Building | Club House | 1 | Good | " " |
| 9 | Camp Administration Office | U-Shaped Office Accommodation | 1 | Fair | " " |
| 10 | Fire Service Station | Office Accommodation | 1 | Good | " " |
| 11 | Security Booth | Single Office | 1 | Good | " " |
| 12 | Bus Stop | Open Stalls | 1 | Good | " " |

| | | | | | |
|----|--------------------------------------|---------------------------------------|---|----------|--------------------------------|
| 13 | Mini Market | Open Stalls | 2 | Fair | Needs Reconstruction |
| 14 | Central Store | Barrel Vault | 2 | Fair | " " |
| 15 | Post Office | Postal Services | 1 | Good | " " |
| 16 | Admin Building | Office Accommodation | 1 | Good | " " |
| 17 | Library Building | Library | 1 | Fair | Needs Renovation |
| 18 | Transport Office Building | Office Accommodation | 1 | Fair | " " |
| 19 | Security Booths | Single Office | 2 | Good | |
| 20 | Mechanical Service Centre | Workshop/Offices | 1 | Fair | " " |
| 21 | Plant Workshop | Workshop/Offices | 1 | Fair | " " |
| 22 | Light/heavy duty Auto Workshop | Workshop | 2 | Fair | " " |
| 23 | Transformer House | Single Room | 1 | Good | |
| 24 | Electrical Maintenance Office | Office Accommodation | 1 | Fair | Needs Renovation |
| 25 | Sole Administrator's Office Building | Office Accommodation | 1 | Good | Needs Reroofing |
| 26 | Finance Office Building | Office Accommodation | 1 | V. Good | |
| 27 | Audit Office Building | Office Accommodation | 1 | V. Good | |
| 28 | Training Workshop | Workshop | 1 | Good | |
| 29 | Vocational Training Centre | Office Accommodation Lecture Rooms | 1 | Good | |
| 30 | Security Office | Single Room | 2 | Good | |
| 31 | Generator House | Single Room | 1 | Good | |
| 32 | Explosive Magazine Building | Store | 1 | Good | |
| 33 | Technical Service Building | Office Accommodation | 1 | Good | |
| 34 | Drawing Studio | Studio | 1 | Fair | Needs Renovation |
| 35 | Laboratory | Mines Laboratory | 1 | Fair | " " |
| 36 | TEAM Office Building | Office Accommodation | 2 | Good | Needs Improvement |
| 37 | Filling Station | Petrol Station | 2 | Obsolete | It can be revived |
| 38 | 4 Bedroom | Duplex | 6 | Good | Two needs complete renovation |
| 39 | Hall | Squash Hall | 1 | Burnt | Needs rebuilding new structure |

| | | | | | |
|----|--|----------------------------|-----|------|------------------------------|
| 40 | 4 Bedroom | Bungalow | 12 | Good | |
| 41 | 3 Bedroom | Bungalow | 28 | Good | |
| 42 | 2 Bedroom | Flat | 154 | Good | 1 Burnt and needs renovation |
| 43 | 1 Bedroom | Apartment | 50 | Fair | |
| 44 | 2 Rooms | Boy's Quarter | 18 | Fair | |
| 45 | 3 Rooms | Boy's Quarter | 21 | Fair | |
| 46 | Single Room | Tenement Building | 6 | Fair | |
| 47 | Single room | Hollywood | 6 | Fair | |
| 48 | School buildings | Staff Primary school | 7 | Good | |
| 49 | School buildings | Staff Secondary school | 11 | Good | |
| 50 | Generator House | Single room | 1 | Good | |
| 51 | Security booth | Single room | 1 | Good | |
| 52 | Primary crusher | 1 storey | 1 | Fair | Needs Renovation |
| 53 | Secondary crusher | 1 storey | 1 | Fair | " " |
| 54 | Beneficiation plant | 1 storey | 1 | Fair | " " |
| 55 | Grinding mill building | Single room | 3 | Fair | " " |
| 56 | 132KVA Substation building | 1 storey | 1 | Good | |
| 57 | Removal substation building | | 1 | Good | |
| 58 | White house office building | Staff office accommodation | 1 | Fair | Needs renovation |
| 59 | Storage yard | Open store | 1 | Good | |
| 60 | Power/utility electrical office/emergency power plant building | Office/store accommodation | 2 | Good | |
| 61 | Substation for storage | | | Good | |
| 62 | Yard | | 1 | Good | |
| 63 | Loading station | | 1 | Good | |
| 64 | Substation for loading | | 1 | Good | |
| 65 | Tailing electrical substation | | 2 | Good | |
| 66 | Repartition bin/Vibration/Pillar building | | 1 | Good | |

| | | | | | |
|----|--|--------------------------|---|------|-------------------|
| 67 | Transfer/removal substations to the loading yard | | 4 | Good | |
| 68 | Thickeners construction | | 2 | Good | Needs resurfacing |
| 69 | Wet screen structure | | 1 | Good | |
| 70 | Electrical substation | | 1 | Good | |
| 71 | Security booth | Single Office | 4 | Good | |
| 72 | Bergeard plant | Office accommodation | 2 | Good | |
| 73 | Clemessy yard | Office building | 2 | Fair | Needs Renovation |
| 74 | Dumez yard | Office building | 2 | Fair | |
| 75 | Dumez restaurant | Restaurant | 1 | Fair | |
| 76 | Sofremines yard | Office accommodation | 1 | Fair | |
| 77 | Ore Rail Line management Building | Office accommodation | 1 | Fair | |
| 78 | Control tower | Storey building | 1 | Good | |
| 79 | Ore Rail Line staffs Office building/workshop | Storey building/workshop | 1 | Good | |
| 80 | Pumping Station | Pump Building/Offices | 1 | Good | |
| 81 | Thickener Construction | | 5 | Good | |

H. OUTSTANDING LEGAL LITIGATION

| S/N O | SOLICITOR NAME | CASES | NATURE OF CLAIM | TOTAL PROFESSIONA L | OUTSTANDIN G BALANCEN |
|----------|--------------------------|--|---|---------------------------|--------------------------|
| 1 | Ismail Usman & Co. | a). Commisioner of Police Vs Aminu O. Ahmed Suit No. | Causing death by dangerous driving. | 85,000.00 | 490,000 |
| | | b). Jibrin A. Daiko Vs NIOMCO Suit No KGS/OK/32/2001 | Claim for repairs effected on typewriter belonging to the Company. | 45,000 | |
| | | c). COPS Vs Yakubu Ismaila. Suit No. HCO/30C/04 | Causing death by dangerous driving. | 55,000 | |
| | | d). Abdul Yekini Otaru & Anor Vs NIOMCO Suit No. KGS/OK/24/2001 | Claim for value of damaged Car. Loss of income. General damages. | 45,000 | |
| | | e). Joseph Damisa Atuaka Vs NIOMCO. Suit No KGS/OK/15/2001. | Wrongful termination of appointment claim for reinstatement and Arrears of Salaries. | 60,000 | |
| | | f). Oseni Momoh Baba Vs NIOMCO Ltd. Yakubu Ismaila Suit No. HCO/30C/04 | This is vicarious liability case whereof the plaintiff claim for the damage of his golf car allegedly | 200,000 | |

| | | | | | |
|----|--------------------------|---|--|----------------------|---------|
| | | | caused by the negligent conduct of the 2nd defendant in the handling of the vehicle on the day of the accident. | | |
| 2 | Danjuma D. Raindams & Co | a). Marlong Advertising Agency Vs NIOMCO. Suit No HCJ/PL/21/98 | Claims for unpaid printing jobs (Calendars) | 55,000 | 55,000 |
| 3. | Salihu Shehu & Co. | a). James Adomu Vs NIOMCO. Suit No FHC/ABJ/CS/92/2000. b). NUMW Vs SEWUN. NIOMCO Industrial Arbitration Panel. Abuja. Suit No NIC/8/2000 | Wrongful termination of appointment and claim for arrears of Salaries. Determination of the right of NIOMCO. Workers to belong to ISSAN & SEWUN as opposed to Metallic & SEWUM as opposed to Metallic & Non Metallic Workers Union. | 60,000 70,000 | 130,000 |
| 4. | Ibrahim Yakubu & Co. | a). Mrs. Onyijimoh Ahmed & 3Ors Vs Mr. Avade Ahmed & NIOMCO. Suit No. KGS/OB/7/2000. b). Kedmore Continental Ltd. VS. NIOMCO. Suit No. HCJ/OB/34T/99 | Claim for payment of death benefits. Claims for payment of contract executed. | 55,000 75,000 | 225,000 |

| | | | | | |
|----|---------------------|---|--|---------|---------|
| | | c). CO P Vs Alhassan Dan-Aliu & 4 ORS. Suit No. CMS/470C/04. | Criminal conspiracy, inciting disturbance, assault and criminal intimidation | 95,000 | |
| 5. | Bello & Co | ITF Vs NIOMCO – High Court of Justice, Ilorin. Suit No. FHC/LKJ/CS/45/2011. | Claim for unpaid statutory contribution to ITF. Bello | 75,000 | 75,000 |
| 6. | Orifumise & Co | Amechi & Partners Vs NIOMCO. Suit No | Claim for unpaid contract job executed. | 48,000 | 48,000 |
| 7. | Sheidu Jim & co. | COP Vs Daniel & 9 Ors. Suit No CMC/OB/37/98. | Criminal conspiracy and Theft. | 40,000 | 40,000 |
| 8. | Fola Ajayi & Co. | Abduikareem A. Shaibu Vs NIOMCO & Aminu O. Ahmed . Suit No. KGS/OK/39/2001. | Claim for damages by estate of victim of accident N3.1m. | 150,000 | 150,000 |
| 9. | Adoga – Ikong & Co. | a). Abdullahi Aliyu Vs NIOMCO. | Claim for 1,027,000.00 Being unpaid professional fees for cases done for NIOMCO. | 200,000 | 290,000 |
| | | b). Abdul Yekini Otaru & Anor Vs NIOMCO Suit No. KGS/OK/24/2001 | Claim for value of damaged Car. Loss of income, General Damages. | 270,000 | |
| | | c). Aminu O Ahmed Vs NIOMCO Suit No. KGS/OB/30/2004 | Claim for reinstatement, Salary arrears | 270,000 | |

| | | | | | |
|----|-------------------------|--|---|--------------|--------------|
| | | | and N300,000,000.0 0 | | |
| | | d). Oseni Momoh Baba Vs NIOMCO Ltd. Yakubu Ismaila Suit No. HCO/30C/04 | This is vicarious liability case whereof the plaintiff claim for the damage of his golf car allegedly caused by the negligent conduct of the 2nd defendant in the handling of the vehicle on the day of the accident. | 200,000 | |
| 10 | D.D Dodo & Co. (SAN) | a). Abdulazeez & 33 Ors Vs NIOMCO Suit No. KGS/OB/08/2005 | Unlawful dismissal reinstatement and claim for arrears of Salaries | 2,100,000.00 | 4,200,000.00 |
| | | b). Sadiku Momoh & Ors Vs NIOMCO Suit No. KGS/OB/12/2005 | Unlawful dismissal reinstatement and claim for arrears of Salaries | 2,100,000.00 | |
| 11 | Lough Chambers | Khadijat Auru Vs NIOMCO and Abdulmaleeq Mohammed & 3 Ors Vs NIOMCO Suit No. NIC/ABJ/2/2011 | Claim of wrongful dismissal and termination of appointments respectively and reinstatement. | 900,000.00 | 400,000.00 |

| | | | | | |
|----|----------------|---|--|----------------------|---------------------|
| 12 | M.T. Musa &Co. | a) Befort Chemicals Nig. Ltd. Vs NIOMCO Ltd., Suit No. HC/OB/12C/2013 | Claim of the sum of N10,757,785.00 in breach of contract being outstanding claim for weighbridge supply. | 1,500,000.00 | 2,500,000.00 |
| | | b) Abuja Electricity Distribution Company Vs NIOMCO. Suit No. HC/OB/71/2014 | Claim for the sum N60,734,543.60 being outstanding bill on electricity supplied | 1,500,000.00 | |
| | TOTAL | | | 10,298,000.00 | 8,603,000.00 |